

## Technical Papers

# Ripping Off the EIFS

Strip the EIFS or repair it; that is the question. The answer is quite simple, and applies to virtually all types of cladding. To begin, one must go beyond the symptoms of water intrusion problems, and find the actual sources of the leaks. As a professional building envelope consultant, I have seen the best and the worst of EIFS. Most EIFS problems, but not all, occur in residential construction. I can tolerate a leak in my office building, because I can always go home, but if my home leaks, it becomes an emotional issue, mostly because there is no where I can escape, and somehow have to deal with the problem. EIFS is not a cladding the average homeowner can repair, and many EIFS repair contractors have not been trained in the forensics and repair. This leads to confusion, and the frustration builds, and the homeowner feels more and more victimized. Who can you go to for competent advice? Maybe it is time for you to become a bit more knowledgeable on the subject of moisture intrusion, so you can protect your most valuable asset, your home. Then you will be able to ask pertinent questions and judge the quality of professional advice, along with the qualifications of cladding contractors.

The professional references are followed with contact information, and there are several local references with e-mail addresses. Let's start with the basic facts about cladding, many of which contradict popular opinion. I suggest you follow a rule that Exterior Design Institute (EDI) instructors use when instructing student EIFS inspectors: "Do not form preconceived opinions. The building will tell you what the source of the problem is, if you pay attention." EDI has trained over 1500 EIFS inspectors, and has several international members.

## TABLE OF CONTENTS

1. Cladding and the building envelope
2. Cause and effect of bad advice
3. Homeowner guide to inspecting EIFS
4. Moisture readings
5. New construction
6. Comparative projects
7. Primary and secondary moisture barriers
8. Quality of construction
9. Conclusions
10. Closing statement
11. Advertising sponsor

## A. CLADDING AND THE BUILDING ENVELOPE

EIFS and other forms of cladding do not normally fail. That is to say, water does not penetrate directly through the surface of the cladding. It penetrates the building envelope. The envelope includes secondary moisture barriers such as felt paper and Tyvek, flashing, and the primary moisture barrier which includes windows, doors, cladding and sealants. The points of water intrusion are identical in virtually every condo or residential project I inspect. The windows were not flashed, and leaked at the lower corners, kick out or diverter flashing was not installed at roof/wall intersections, allowing roof run off to get behind the cladding, and decks were not properly flashed. If those conditions did not exist, there would be no water intrusion.

**Here are some things for you to consider:**

1. Very few of the general contractors, building residential or light commercial, including condos and apartments, in this area, have had the opportunity to be trained in the basics of moisture intrusion prevention. They rely heavily on their subcontractors to install the cladding components according to manufacturer specifications.
2. EIFS is not a subject taught to student engineers or architects.
3. The local government paid building inspector, contrary to popular belief, is not responsible for assuring the water tightness of the building envelope. Much of their time is spent inspecting work completed by licensed contractors, yet, only a handful of the inspectors is required to pass any type license exams, to test their knowledge. Local building departments, in their defense, have the same problem most construction companies have; finding skilled employees.
4. There are lots of condos, apartments and residential projects under construction, which do not have EIFS, but lack a viable secondary moisture barrier and flashing, and will experience typical moisture intrusion problems. I just recently opened the wall on a condo, completed 4 years ago, which is clad with vinyl siding, and is experiencing moisture intrusion, wood rot, and mold growth...
5. All wood frame construction shrinks. The wood dries and the building weight compresses cross grain members. A two story building will shrink ¼ to ½ inch in one year. This means all of the structural framing gets smaller, but the plywood or OSB does not shrink. The entire weight of the building transfers to the sheathing, and eventually the sheathing buckles at the second floor line, thus the bulges you can see at the second floor line, so common to wood frame construction. There should be a one inch gap in the sheathing horizontally at the floor line, to allow for the compression. The compression joint then must be installed in the cladding, at the floor line, to absorb the shrinkage or there is potential for a breach in the building envelope.
6. Residential EIFS, in the 1990's, was installed for less than \$4.00 sq. ft., while commercial EIFS cost about \$6.00 sq. ft. Material price was the same for both. The \$2.00 savings in residential, came from the omission of flashing and sealants, and disregard for manufacturer specifications and application instructions.
7. The residential building envelope is usually flawed. If it can leak, it will leak All EIFS should be inspected by an independent, trained and certified inspector, during all phases of application. Further, all residential construction should have a secondary moisture barrier.
8. Dateline, often referenced, videoed over 20 hr. of professional interviews, which contradicted the story they presented. The producers apparently cut them because they would not, in their opinion, attract the most viewers. North Carolina, also often referenced, has banned barrier EIFS, but approves drainable EIFS, which is the only product EIFS manufacturers sell into the residential market today.

## B. CAUSE AND AFFECT OF BAD ADVICE

There are only three of 3000+ projects, in my 30 years experience, where I was involved in some capacity, that EIFS had to be completely removed. &nbns;Most EIFS clad structures do not have to be stripped, at least from a technical perspective. I seldom hear of a residential building being stripped, if the cost is borne by the owners.

In my immediate market area, a local architect was quoted in the daily paper, as saying he has seen at least seven EIFS clad communities struggle with water damage behind EIFS. One of those projects, where he recommended the EIFS be completely stripped and the buildings clad with cement board siding, was photo documented during the envelope demolition. As fate would have it, Austin Scanlon, Chairman, EDI ([austino3@eifshotline.org](mailto:austino3@eifshotline.org)), was inspecting a project directly across the street while the EIFS was being stripped. Austin is a master estimator and quantity surveyor. So, while inspecting the repair progress of his project, he photographed the EIFS rip off across the street. Austin stated: " 95 % of the sheathing on Lesner Villas had no moisture damage, and there was no justification to rip it off. The only moisture damage was at poor quality leaking windows, below improperly flashed decks, and where diverter flashing at the roof/wall intersection was missing." My colleagues at EDI, including nationally recognized experts in building envelope science, would never even consider making such an unscientific claim to categorically strip off the EIFS cladding, without substantial forensic investigation. The following individuals' resumes can be accessed by going to the EDI home page, click on instructors, then click on individual names:

1. Austin Scanlon, Chairman, EDI, Virginia
2. Jim Whalen, President, EDI, Virginia
3. Douglas Creed, PE, South Carolina
4. Ronald Hoffman, PE, Colorado
5. David Kimball, Chemist, Michigan
6. Dennis Rose, Chemist, MBA, Florida
7. Bryan Weight, PE, Oregon
8. Robert J. Kudder, PhD, PE, Illinois

I further reference Mr. Sheldon Leavitt, PE, [sjl@leavittassoc.com](mailto:sjl@leavittassoc.com), Norfolk, Virginia

A brief inspection can alert you to potential trouble spots.

1. Check roof / wall intersections to see if an angled piece of flashing has been installed to divert the flow of water away from the vertical wall
2. Check the lower corners of windows for any gaps in the corner miters, and probe the sealant to determine if it is still flexible.
3. Look for any bulges at the second floor line.
4. Carefully check your deck, if it is wood frame and attached to the house. There should be visible flashing and no sign of wood rot.
5. EIFS should not be installed below grade, so when replacing mulch, first remove the old mulch.
6. If you suspect a problem, go to [www.eifshotline.org](http://www.eifshotline.org), and find a qualified inspector in your area. 85% of all remediation, costs less than \$1500, and is usually a maintenance issue. Keep in mind, water intrusion is cumulative. The longer water penetrates the building envelope, the greater the potential damage. Go to [www.moisturewarranty.com](http://www.moisturewarranty.com), click on "flash video presentation, then click on understanding the problem
7. Be aware that any inspector who proposes to remediate and inspect on the same project, is in conflict of interest.

## D. MOISTURE READINGS

Moisture content of wood must exceed 19.5% for the algae, which causes wood rot, to exist. Kiln dried lumber is dried to 19%, prior to shipment to lumber yards. There are so many references to moisture content of wood by so many scientists, testing labs and agencies, anyone who states a 10% moisture reading in wood or OSB sheathing should be considered an elevated reading, is simply making up the rules and completely disregarding an army of highly trained experts. Likewise, any inspector or consultant who states any moisture reading in any type of wood, exceeds 40%, has their moisture meter probes submerged in a glass of water, or is using the wrong equipment. Without a doubt, this individual is not a qualified moisture analyst. Most grades of construction lumber and sheathing cannot absorb more than 30 -35% moisture before reaching total saturation. The harder the species, the lower the saturation point. Why? The wood fibers take up the rest of the space. There is simply no more room for water without removing the wood fibers.

## E. NEW CONSTRUCTION

EIFS was the product of choice in high end residential construction during most of the '90's, because of the dynamic design potential and curb appeal. The problems learned about EIFS in residential construction, have been addressed in the EDI Integrity Program. (link to integrity) I will be recladding my older home in the next year, and will be removing the brick, which adds a great deal of weight in sandy soil conditions, and installing a drainable EIFS, following the EDI Integrity Program requirements. The EDI Integrity Program addresses potential oversights of all responsible parties in the EIFS cladding chain. Manufacturers in this program are required to issue a 10 year labor and material warranty. Applicators must complete certification training, be sponsored by an EDI registered manufacturer, sign a three year blanket labor warranty, and then will qualify for liability insurance underwritten by Lloyd's. All projects must be inspected by an EDI certified Quality Control Consultant, paid by the EDI Loss Prevention agents, which helps avoid collusion. All parties must sign a binding arbitration clause to qualify for the Integrity Program. This program is not designed to protect the applicator or manufacturer. It is designed to protect the building owner.

## F. COMPARATIVE PROJECTS

A local condo development, clad in EIFS, built 18 years ago, typifies developments throughout the country. The condo association hired architectural firm to advise them on how repair leaks in their buildings. The recommendation was to remove all of the EIFS and replace it with cement board siding. They followed the advice, at a cost of \$52,000 per unit.

I have been involved the remediation of several condo projects locally, with substantially different unit owner costs, than that quoted above:

1. Harbor View- \$3000 per unit. Reference: John Samuel, association President. Contact: [j.b.Samuel@worldnet.att.net](mailto:j.b.Samuel@worldnet.att.net)
2. Harbor Point- \$9000 per unit. Reference: Carol Van Gilder, association VP. Contact: [carolv@clloydjohnson.com](mailto:carolv@clloydjohnson.com)
3. Linkhorn Bay- \$1000 per unit. The cost was borne by the Builder. Reference: C.J. Shaughnessy, association President. Contact: [cjshauh@cox.net](mailto:cjshauh@cox.net)

Values on all of these condos have dramatically increased, so resale has not been affected by EIFS cladding. I was also asked to look at the \$52,000 per unit project, by one of the bidders, and estimated the remediation cost to be about \$800,000 or less than \$16,000 per unit, with a 10 year labor and material warranty from the manufacturer.

All of these condo projects experienced the identical problems. They lacked kick outs, deck flashing was not installed properly, sealants had failed or had never been installed. The older the project, if not properly maintained, the higher the cost to fix the cumulative damage. The condo owners who spent \$52,000 per unit, did so because they chose to listen to some very costly advise.

My message is beware of the engineer, architect or consultant who says you must strip all of the EIFS, and definitely get a second opinion. If you do need to fix your EIFS home or condo, be absolutely certain the contractor is insured, and has a current valid contractor license. Good construction is a must to protect home and building owners. The local building codes may not require a secondary moisture barrier, however, the International Residential Building Code, R703.1, is a part of most the State code and requires ...."water resistant barrier behind the exterior veneer"....

## G. PRIMARY AND SECONDARY MOISTURE BARRIERS

Tyvek, felt paper or liquid applied membranes are all components of the secondary moisture barrier. Add flashing, windows, doors, and the walls should be able to shed water without any moisture reaching the sheathing or framing. Next comes the cladding and caulking (sealant).

My test equipment of choice for the secondary moisture barrier is a garden hose. If the secondary barrier leaks, it is a waste of time to put in on at all, which, by the way, is the reason many cladding installers don't bother with it. On the other hand, if it performs as it should, shedding all water, then it really doesn't matter what cladding is used, the sheathing and structure are protected.

The only work left, is to properly install the primary moisture barrier according to details and specifications. If this is done correctly, the secondary moisture barrier remains a dormant backup to wear and tear of the cladding. All cladding does need some sealant, depending on the cladding used. Never use acrylic caulking on the exterior. It has an anticipated life of less than two years, and a 10% movement capability. Use only urethane or silicone sealants. My material of choice is Dow 790, which is a pure silicone, with =100% and -50% movement capability. The anticipated life is 20+ years.

## H. QUALITY OF CONSTRUCTION

1. Many cladding contractors sub contract their work to "piece work" contractors. This means the contractor you hired doesn't actually do the work, but pays another crew by the square foot, to install the cladding. They are often unsupervised.
2. Many cities and towns have set policy requiring an independent third party EIFS inspector to sign off on a project before they will issue a certificate of occupancy.
3. Residential contractors may lack on site supervision of sub contractors, or have inexperienced supervision.

## I. CONCLUSIONS

When your car doesn't start, you don't blame the key. You find out why it won't start or call a competent mechanic, then get the problem fixed. When your home leaks, it is a symptom of the problem. Leaky cladding is a symptom and you need to fix the actual problem. Something in the building envelope is usually the problem, unless, of course, you have a burst pipe. If you have leaks in the ceiling, it may be the roofing, but it may also be flashing or clogged gutters.

Treat your home the same way your doctor treats your medical ailments. Symptoms lead to causes, and causes are what must be treated. Don't waste your time treating the symptom, it will just mask the root cause and could lead to more severe problems.

If you own an EIFS home, don't panic. If you plan to sell your EIFS home, get it inspected prior to putting it on the market, as any professional real estate salesman would suggest. If you plan to buy an EIFS home, require an inspection as a condition of purchase.

The EIFS industry took in the '90's, was negative. But it was very similar to the problems experienced by the rubber roof industry in the '80's. Their solution was to require independent certified roof inspectors to sign off on every installation, and the problems disappeared.

EIFS clad homes, buildings and condos can be remediated at a fraction of the cost of complete removal. Community and condo boards of directors can be held accountable for meeting their fiduciary responsibilities. They must accumulate a reasonable amount of funds to cover the costs of long term as well as short term maintenance. If you do choose to sit on a board, be sure E & O and liability insurance is in place for directors and officers. There are many competent attorneys specializing in just this sort of situation. Check with your real estate professional for referrals.

If your association is responsible for more than 4 units, hire a management company, who can guide you through the procedures and keep you out of trouble.

## J. CLOSING STATEMENT

Many of the buildings you drive by each day are clad with EIFS. Hotels, motels, malls, churches, office buildings, most of Las Vegas, and some of the largest and most prestigious homes are all EIFS. If it is particularly fancy, has a lot of architectural detail, large monolithic surfaces, it is probably EIFS. It is one of the most widely used claddings in the commercial market. They do not have the typical home or condo owner problems; because the commercial projects generally have lots of supervision. The same could be said about the residential market, if every project got an independent inspection.

Finally, do not blame the cladding, blame the building envelope, or you will be just another EIFS building owner getting ripped off.



© Copyright Exterior Design Institute. All Rights Reserved.

Developed and powered by [outsorce IT](#)